



This is a picture of the actual accident site. The shoring end frames with the leveling screws jacks are extended to level the shoring. The distance from the shoring end frame to the wall is approximately 8 feet.



Close-up view of the shoring with the leveling screws jacks extended.



The floor in this area is wet with approximately a quarter inch of water.



Another view of the wet floor and shoring.



This is a re-enactment of the injury -- this employee was a witness to the accident



This picture shows the re-enactment position of the employee that fell. It is presumed that as the employee slipped and lost his balance, he struck the floor with his feet, and then stumbled backwards and hit the wall with his head.