




Note  
blackened  
and  
melted  
plastic  
along  
top.



White circle in middle is the ignition point.



Location of relay with cover removed.



Internal examination of the relay components shows temperature-related discoloration of the coil. This indicates temperatures over 1400 F. Molten metal indicates electrical arcing. Sparks were likely.